

## Various combinations of dial comparators

- •By combining various brackets and arms, the outside diameter and thickness can be measured simultaneously.
- ·Select optimal parts to suit your needs.



 $$\operatorname{\textbf{PH-3S}}$$  Combination of the upper metal fixture for PH-3 and

the lower metal fixture and base for the universal type)

Combination of two pieces of small-sized universal dial comparators

