



Stock No.563

## Bench center (type-P)

- These small-sized eccentricity checkers can be used on a surface plate or a table.
- \* A dedicated stand is attached to all models. A dial gauge and a test bar are not attached.
- \* Custom-made eccentricity checkers are also available by special order to suit your dimensional requirements.



■ Dimensional drawing Unit : mm



Material : Cast iron (Bed, Head)  
 Package : Reinforced cardboard  
 Accessories: Certificate of inspection

### Configuration of product code

563 - P1L  
 |  
 P1L → P-1  
 P2L → P-2  
 P3L → P-3

Product No	Stock No	Model	L (mm)	W (mm)	H2 (mm)	L1 (mm)	H1 (mm)	Parallelism between center (μ m)	Applicable center	Weight (kg)
55-2-1	563-P1L	P-1	380	120	65	150	110	5.0	MT-1	14
55-2-2	563-P2L	P-2	420	120	72	200	110	5.0	MT-1	16
55-2-3	563-P3L	P-3	530	130	90	300	110	5.0	MT-1	20

## About Dial Stands

A dedicated dial stand is attached to the standard-type and type-P eccentricity checkers. (The figure on the left shows Type-P.) Depending on inspection conditions, use of multiple dial stands makes measurements faster and insures higher accuracy. A stand and fixtures for a lever-operated dial gauge are also available by order. (See the figure on the right.)

